

Regional Communications System
Network Incident Log
September 1999

9335 Hazard Way, #105
San Diego, CA 92123
Tel. (858) 694-3663
Fax (858) 694-3433
Web site: <http://www.co.san-diego.ca.us/rcs>

●	Scheduled Maintenance
⚙	Unscheduled Maintenance
▼	System Outage

	Date Time	System(s) Impacted	Incident Summary
●	9-01-99 1500 9-02-99 1700	North Loop Microwave System (PSC/Lake San Marcos)	Momentary crackling noises on console as a result from installing loop protection switches.
●	9-02-99 0900-1200	South Simulcast Site (Otay Mountain)	Replaced bad interface panel. Actual downtime less than 5 minutes.
●	9-02-99 0800-1200	Trunked Radio Site (Alpine Heights)	Removed and replaced the UPS. Reduced coverage. Site was off the air for 30 minutes.
●	9-16-99 9-21-99	RCS SmartZone (Lyons Peak)	SDG&E replaced power lines feeding at Lyons Peak. Minimal impact to users. Site remained on the air. Back-up generator to power site while commercial power was off.
●	9-20-99 0000 - 0040	RCS 800 MHz (PSC)	Upgrade of SmartZone controller. System returned to wide trunking as of 0040. Resumed wide area operations. Maintained back up radios in operational status as a fallback.
▼	9-30-99 1745	South Simulcast Microwave (USCD/San Ysidro)	Microwave path outage. No impact to users. Loop switch system worked as designed. For information only.